

SL 20 Exit Closed (Exit 8B)

Contractor will be performing a closure at IH 35 Northbound frontage road at Exit 8B. SL 20 exit from IH 35 Northbound mainlanes (Exit 8B) will be closed.

All traffic will need to take a detour thru Exit 2B on Carriers Dr. use the traffic signal and turn left into IH 35 Southbound frontage rd. and merge back into IH 35 southbound and continue into Mile intersection and use the traffic signal to go into the SL 20 Eastbound frontage rd.

